



Vehicle History Report™

US \$39.99

1987 BMW 325IS AUTOMATIC

VIN: WBAAA2304H3111683
COUPE
2.5L I6 F SOHC
GASOLINE
REAR WHEEL DRIVE



Damage reported



12 Service history records



38 Detailed records available



117,561 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 9/3/20 at 8:55:21 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Title History

CARFAX guarantees the information in this section

Summary

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon



Guaranteed
No Problem

Not Actual Mileage | Exceeds Mechanical Limits



Guaranteed
No Problem



GUARANTEED - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back.
[Register](#) | [View Terms](#)



Additional History

Not all accidents / issues are reported to CARFAX

Summary

Total Loss

No total loss reported to CARFAX.



No Issues Reported

Structural Damage

CARFAX recommends that you have this vehicle inspected by a collision repair specialist.



No Issues Reported

Airbag Deployment

No airbag deployment reported to CARFAX.



No Issues Reported

Odometer Check

No indication of an odometer rollback.



No Issues Indicated

Accident / Damage

Damage reported on 07/03/2020.

Damage Reported

Manufacturer Recall





No open recalls reported to CARFAX. Check with an authorized [BMW dealer](#) for any open recalls.




















No Recalls Reported



Detailed History

Mileage	Source	Comments
04/29/1990	California Motor Vehicle Dept.	Title issued or updated - Loan or lien reported
10/15/1991	53,569 California Inspection Station Cutler, CA	Passed emissions inspection
09/24/1993	65,899 California Inspection Station Cutler, CA	Passed emissions inspection
12/28/1995	77,458 California Inspection Station Cutler, CA	Passed emissions inspection
10/13/1997	84,574 California Inspection Station Cutler, CA	Passed emissions inspection
11/04/1999	California Motor Vehicle Dept. Tulare, CA	Title issued or updated
12/12/2000	99,421 Service Facility Cutler, CA	Vehicle serviced
		
12/12/2000	California Inspection Station Cutler, CA	Passed emissions inspection
04/27/2001	Howell's Service Center Tulare, CA 559-688-6621	Vehicle serviced - Maintenance inspection completed - Engine/powertrain computer/module checked - Oil and filter changed
		
10/09/2002	109,531 California Inspection Station	Passed emissions inspection
12/01/2002	California Motor Vehicle Dept. Tulare, CA	Title issued or updated - New owner reported
01/21/2003	California Motor Vehicle Dept. Three Rivers, CA	Title issued or updated - Registration updated when owner moved the vehicle to a new location
08/10/2004	California Inspection Station	Failed emissions inspection
08/10/2004	Vehicle Repair Center	Vehicle serviced - Top engine cleaned
		
08/10/2004	California Inspection Station	Passed emissions inspection
08/10/2004	California Inspection Station	Passed emissions inspection
08/25/2006	California Inspection Station	Passed emissions inspection
03/09/2010	Wilson Foreign Auto Repair Visalia, CA 559-739-1608	Vehicle serviced - Air filter replaced - Oil and filter changed - Spark plug(s) replaced - Transmission fluid changed - Transmission filter replaced - Driveshaft serviced - Emblem replaced
		

11/22/2010		California Inspection Station Three Rivers, CA	Failed emissions inspection
07/19/2011		California Inspection Station Visalia, CA	Passed emissions inspection
12/13/2012		California Inspection Station Woodlake, CA	Passed emissions inspection
03/11/2015		California Inspection Station San Luis Obispo, CA	Failed emissions inspection - Designated GROSS POLLUTER
03/19/2015		California Inspection Station San Luis Obispo, CA	Passed emissions inspection
05/14/2015		California Motor Vehicle Dept. San Luis Obispo, CA	Registration updated when owner moved the vehicle to a new location
09/26/2017		California Motor Vehicle Dept. Tulare, CA	Title issued or updated - Duplicate title issued
11/08/2018	115,000	Central Coast Auto Center Morro Bay, CA 805-772-1249   13 Customer Favorites	Vehicle serviced
11/08/2018	115,310	California Inspection Station Morro Bay, CA	Passed emissions inspection
11/09/2018		California Motor Vehicle Dept. Cambria, CA	Title issued or updated - New owner reported
01/31/2019	115,362	German Auto San Luis Obispo, CA 805-543-7473 germanautoslo.com   4.4 / 5.0 17 Verified Reviews   40 Customer Favorites	Vehicle serviced - Antifreeze/coolant flushed/changed
05/11/2019		Tennessee Motor Vehicle Dept.	Vehicle purchase reported
09/16/2019	115,745	Autosport Werks Broomfield, CO 303-460-9900   4.9 / 5.0 36 Verified Reviews   66 Customer Favorites	Vehicle serviced - Two wheel alignment performed
10/11/2019		Tennessee Motor Vehicle Dept. Nashville, TN Title #11900352520	Title or registration issued - New owner reported - Vehicle color noted as Black

<p>12/09/2019</p> <p>117,509</p> 	<p>German Motorworks Nashville, TN 615-383-3361 https://germanmotorworksnashville.com</p> <p>★ 5.0 / 5.0</p> <p>14 Verified Reviews ✓</p> <p>♥ 17 Customer Favorites</p>	<p>Vehicle serviced</p> <ul style="list-style-type: none"> - Tire(s) balanced - Engine mount(s) replaced
<p>12/13/2019</p> <p>117,542</p> 	<p>German Performance Options Nashville, TN 615-248-9466 gpotuning.com/</p> <p>★ 4.8 / 5.0</p> <p>41 Verified Reviews ✓</p> <p>♥ 517 Customer Favorites</p>	<p>Vehicle serviced</p>
<p>01/24/2020</p> <p>117,545</p> 	<p>German Performance Options Nashville, TN 615-248-9466 gpotuning.com/</p> <p>★ 4.8 / 5.0</p> <p>41 Verified Reviews ✓</p> <p>♥ 517 Customer Favorites</p>	<p>Vehicle serviced</p> <ul style="list-style-type: none"> - Exhaust system checked - Thermostat housing/gasket replaced - Tie rod end(s) replaced - Valve cover gasket(s) replaced - Camshaft tower seal replaced - Differential checked - Sway bar link(s) replaced - CV boot(s) replaced - Intake manifold gasket(s) replaced - Two wheel alignment performed - Clutch slave cylinder replaced - Clutch master cylinder replaced
<p>03/13/2020</p> <p>117,558</p> 	<p>German Performance Options Nashville, TN 615-248-9466 gpotuning.com/</p> <p>★ 4.8 / 5.0</p> <p>41 Verified Reviews ✓</p> <p>♥ 517 Customer Favorites</p>	<p>Vehicle serviced</p>
<p>04/03/2020</p> <p>117,561</p> 	<p>German Performance Options Nashville, TN 615-248-9466 gpotuning.com/</p> <p>★ 4.8 / 5.0</p> <p>41 Verified Reviews ✓</p> <p>♥ 517 Customer Favorites</p>	<p>Vehicle serviced</p> <ul style="list-style-type: none"> - Maintenance inspection completed - Oil and filter changed
<p>07/03/2020</p> 	<p>Damage Report</p>	<p>Damage reported</p> <div style="text-align: center;">  </div> <div style="border: 1px solid black; padding: 10px; margin-top: 10px;"> <p>Not all damage is caused by an accident. Get the car inspected before you buy. Learn more</p> </div>

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.

Damage Indicator

Damage can be a result of many different types of events. Examples include contact with objects (other cars, trees, traffic signs, road debris, etc), vandalism, or weather-related events. Not every damage event is reported to CARFAX. As details about the damage event become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 9/3/20 at 8:55:21 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

Failed Emissions Inspection

The emissions check performed during a vehicle inspection indicated the vehicle was emitting more than allowable emissions standards and/or had missing or modified parts. Repeated failed emissions records can indicate engine problems and CARFAX recommends you have the vehicle inspected.

Gross Polluter

A Gross Polluter is a vehicle that fails an emissions inspection with below-standard scores. These vehicles can pollute as much as 18 times more than a vehicle that passes an emissions inspection. It is illegal to drive or sell a gross polluting vehicle in California, and it cannot be registered with the DMV. CARFAX recommends checking the latest Vehicle Inspection Report to confirm the proper repairs have been completed before purchasing.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



facebook.com/CARFAX



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. CARFAX®

© 2020 CARFAX, Inc., a unit of IHS Markit. All rights reserved.

Covered by United States Patent Nos. 7,113,853; 7,778,841; 7,596,512, 8,600,823; 8,595,079; 8,606,648; 7,505,838.

9/3/20 8:55:21 AM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 1987 BMW 3 SERIES vehicle (VIN: WBAAA2304H3111683), which is based on information supplied to CARFAX and available as of 9/3/20 at 9:55 AM (EDT).

Customer Signature

Date

Dealer Signature

Date